



ICT International Pty Ltd

Enabling better global research outcomes in soil, plant & environmental monitoring

ICT International PSY1 Stem/Leaf Psychrometer Chamber Exchange Program

When a Psychrometer Chamber RMA is submitted, typically for damaged thermocouples, ICT International will send a replacement chamber upon receipt of your damaged chamber and payment, in order to minimise downtime.

The cost of the replacement chamber is US\$280 + any freight charges.

In order to enable payment, a quotation will be issued with bank details once freight arrangements have been made.

All chambers will require calibration, regardless of if they are the original chamber with replaced thermocouples or an exchange chamber. See [the Psychrometer Calibration Manual](#) for information on calibration.

Calibration solution is a component of the PSY Installation Kit, or can be ordered with the replacement chamber if necessary.

ICT International Pty Ltd

ABN: 75 002 372 554

PO Box 503 Armidale NSW 2350 Australia

Phone: 61 2 6772 6770 Fax: 61 2 6772 7616

Email: sales@ictinternational.com www.ictinternational.com.au